

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43525 Main Street: MILHAVEN_LN Cross Street: TANAGER_PARK_DR Location: SW

ADA ID: CDB650ADB043 Ramp Type: Para Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

TANAGER PARK DR

Stop Condition-Street 1

StopSign

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

CURB GAP 1.0

PROW/ADA:

R304.3.2

Total Cost: \$ 1600.00

| Compliance Description Data Compliance Description Data | | | | | | |
|---|------------|----------------------|------|------------|-----------------------------|------------|
| | N/A | Ramp Length LT (in) | 70.0 | N/A | Ramp Length RT (in) | 59.0 |
| | Yes | Ramp Width LT (in) | 59.0 | Yes | Ramp Width RT (in) | 60.5 |
| | No | Ramp Slope LT (%) | 9.1 | No | Ramp Slope RT (%) | 9.6 |
| | Yes | Ramp XSlope LT (%) | 0.2 | Yes | Ramp XSlope RT (%) | 1.9 |
| | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | N/A N/A | 0 0 () | N/A | N/A N/A | DWS Contrast? | N/A |
| | N/A N/A | Landing Width (in) | N/A | N/A N/A | DWS Length (in) | N/A N/A |
| | | Landing Slope (%) | | | 5 () | |
| | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | N/A | Shared Landing? | N/A | | 0 " 0 "0" | |
| | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | | X Walk 1 Direction | To N | | X Walk 2 Direction | N/A |
| | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | X Walk 1 Slope (%) | 1.1 | | X Walk 2 Slope (%) | N/A |
| | | X Walk 1 X Slope (%) | 0.2 | | X Walk 2 X Slope (%) | N/A |
| | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | N/A | | | N/A |
| | | | | Yes | Surface Condition? (G/P) | Good |
| | | | | N/A | Curb Slope (%) | 18.4 |
| | | | | | | |
| | | | | | | |





