

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



								Location	NW
Intersection ID: 8526	Main Street: LANEWOOD_PL			Cross Street: WESTRIDGE_DR				Location:	
ADA ID: CDECA8EC9FB4	DA ID: CDECA8EC9FB4 Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Dat		Data	a Compliance Description		Data
		Remove & Replace Curb Ra	amp With	N/A	Ramp Length (in)	64.0	Yes	BlendTrans Slope (%)	3.7
		Two New Directional Ramps	-	No	Ramp Width (in)	45.0	No	BlendTrans XSlope (%)	2.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E PROCE DR		GTR GAP 2.0		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
WIESUUM & P				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		2		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.	.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		, , , ,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
All the second second	the a -				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	1 2008-				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name WE	STRIDGE DR				X Walk 1 Slope (%)	10.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.4		Clear Space?	N/A
					Road X Slope (%)	10.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.5