

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28850	Main Street: BERWICK_RD			Cross	Street:	FAIRSTONE_AV	Location:	NW		
ADA ID: CE0A42CBEE97	Ramp Ty	Ramp Type: BlendTrans2			Pass/Fa	ail: Pass Ove	o Severity Score:	17.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Curb	Ram	with	N/A	Ramp Length (in)	93.0	Yes	BlendTrans Slope (%)	1.9
		Two New Directional Ra		•	Yes	Ramp Width (in)	52.0	No	BlendTrans XSlope (%)	2.9
		Equivalent.	•		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
					N/A	Flare Slope LT (%)	-	N/A	Flare Slope RT (%)	3.5
					N/A	Flare Traversable LT	? <b>No</b>	N/A	Flare Traversable RT?	No
		1			N/A	Landing Length (in)	N/A	No	DWS Provided?	No
FAIRSTONE_AV		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	) <b>N/A</b>	N/A	DWS Full Width?	No
	12 11-1				N/A	Landing Curb? (Y/N)			DWS Offset (in)	N/A
				N/A	Shared Landing?	, No				
	PROW/ADA:			Yes	Gutter Ponding?	No		Gutter Slope (%)	3.9	
	Not Found, R304.5.3, R3	05 D	30272	No	Gutter Lip Ht (in)	0.5		Gutter X Slope (%)	0.0	
and the second second	Not i build, R304.5.5, R5	0 <b>5</b> , R	502.7.2	N/A	Painted X Walk1?	No		Painted X Walk2?	No	
					X Walk 1 Direction	To S		X Walk 2 Direction	To E	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	FAIRSTONE AV					X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	0.7
Stop Condition-Street 1	None					X Walk 1 X Slope (%)			X Walk 2 X Slope (%)	0.7 3.7
Steet 2 Name	BERWICK RD				N/A	Ramp inside XWalk1		N/A	Ramp inside XWalk2?	3.7 N/A
					N/A			N/A		
Stop Condition-Street 2	StopSign					Road Slope (%)	0.1	l	Clear Space?	Yes
						Road X Slope (%)	2.9		Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A	1		N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.4