cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10025497 Main Street: E_MARTIN_LUTHER_KING_JR_GBV/ss Street: N/A								Location:	Е
ADA ID: CEA0F3270631					ail: Fail Overall		8.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
NOT 2 14		Possible Solutions:						Compliance Description	
8	Rei	move & Replace Entire I	Ramp.	N/A	Ramp Length (in)	68.0	Yes	Ramp Slope (%)	7.8
	10,00			No	Ramp Width (in)	42.0	Yes	Ramp XSlope (%)	0.9
	19 Jah			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 . A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	A.			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Bas a	the e			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surve	eyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E. Contraction	N/A	4		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		-		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second	CA 10			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
		W/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
the has a second					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	136.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name MARTIN LUTHER KING JR BV					X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	YieldSign				X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total	Cost:	\$ 1850.0	0	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A