

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•		-					/
Intersection ID: 4578	Main Sti	Main Street: OLD_STATESVILLE_RD				HOLLY_VISTA_AV	Location:	NW		
ADA ID: CF135CF8B1A4	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description Data C				Compliance Description	
TOLLY, VISITAL AND	en al anticipation de la company de la compan	Remove & Replac	o Entiro Ramo		N/A	Ramp Length (in)	60.0		Ramp Slope (%)	9.4
		Remove & Replat			No	Ramp Width (in)	42.0		Ramp XSlope (%)	3.5
					N/A	Flare Type LT	N/A		Flare Type RT	N/A
		5			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A		,	
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.	1 D304 2 2		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
		R304.5.3	.5.1, 1, 1, 1, 1, 1, 2, 2, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
and this						X Walk 1 Direction	To S		X Walk 2 Direction	N/A
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HOLLY VISTA AV	-				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	 N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
	N/A					Road X Slope (%)	N/A		Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type	197		Storm Grate/Utility Type	11/5
		13tal 000t.	ΨI			Coolidolori Type	N/A		clothi Grato, Guilty Type	N/A
							IN/A			11/17

Yes Surface Condition? (G/P)

Good

