

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13795Main Street:DENBUR\_DRCross Street:LUSTERLEAF\_HOLLY\_RDLocation:NEADA ID: CF5DB50F1E95Ramp Type:ParaInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:26.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name

LUSTERLEAF HOLLY RD

Stop Condition-Street 1

StopSign

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

LT RP < 5%

PROW/ADA:

R304.5.3, R304.3.2

Total Cost: \$ 1600.00

Compliance Description Data Compliance Description Data					
N/A	Ramp Length LT (in)	52.5	N/A	Ramp Length RT (in)	42.0
Yes	Ramp Width LT (in)	59.5	Yes	Ramp Width RT (in)	60.5
Yes	Ramp Slope LT (%)	0.3	No	Ramp Slope RT (%)	12.2
No	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	4.2
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A	IN/A	DWS Offset (III)	IN/A
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No.	N/A	Painted X Walk2?	N/A
IN/A	X Walk 1 Direction	To S	IN/A	X Walk 2 Direction	N/A N/A
N/A		N/A	N/A		N/A N/A
IN/A	X Walk 1 Slane (%)		IN/A	X Walk 2 Width (in)	
	X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	N/A
NI/A	X Walk 1 X Slope (%)	3.8	NI/A	X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	12.3





