

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11921 Main Street: COUNTRY CLUB DR **Cross Street: VENTOSA_DR** Location: **Overall Compliance: No ADA ID: CFCFBAF8421C** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution



VENTOSA DR Street 1 Name StopSign Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

i cocibio colution	
Possible Solutions:	2
Remove & Replace Entire Ramp.	ı
	1
	ı
	ı
	ı
	ı
Surveyor Notes:	ı
N/A	ı
	ı
	ı
	ı
PROW/ADA:	ı
Not Found, R304.5.1, R304.2.2,	ı
R304.5.3	ı
	1

Total Cost: 1850.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	11.4		
No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	3.6		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
3							





