

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10031407 Main Street: MCALPINE_STATION_DR Cross Street: N/A Location: SW **Overall Compliance: No** ADA ID: D0FB3A297A27 Ramp Type: Directional1 Initial Pass/Fail: Pass **Severity Score:** 0.25

Codes/Mitigation Info/P

Field Measurements/Component Compliance



Street 1 Name	N/A
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solution		
Possible Solutions:	Comp	liance De
Remove & Replace Entire Ramp.	N/A	Ramp Le
·	Yes	Ramp W
	Yes	Ramp SI
	No	Ramp XS
	Yes	Flare Ty _l
	N/A	Flare Slo
Surveyor Notes:	N/A	Flare Tra
N/A	Yes	Landing
	Yes	Landing
	Yes	Landing
	No	Landing
PROW/ADA:	N/A	Landing
R304.5.3, R305.2	N/A	Shared L
	Yes	Gutter P
	Yes	Gutter Li
	N/A	Painted 2
		X Walk 1
		X Walk 1
		X Walk 1
		V M-II. 4

	10
	Chairma A



Total Cost:



1600.00

_					
Comp	liance Description	Data	Com	pliance Description	Data
N/A	Ramp Length (in)	95.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	60.0	Yes	Grade Break Slope (%)	1.3
Yes	Ramp Slope (%)	1.5	Yes	Grade Break XSlope (%)	1.9
No	Ramp XSlope (%)	2.9			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	64.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.4	Yes	DWS Length (in)	24.0
No	Landing X Slope (%)	2.4	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	28.0
N/A	Shared Landing?	No	No	DWS Offset RT (in)	5.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.4
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.3
N/A	Painted X Walk1?	No		Road Slope (%)	0.7
	X Walk 1 Direction	To NE		Road X Slope (%)	0.6
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.6	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
		N/A	N/A	Curb Slope (%)	12.4