

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9617	Main Street: CATALINA_AV			Street:	W_28TH_ST	Location:	NW			
ADA ID: D308C62A8342	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No						
			Initial						13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance Compliance Description Data						
1 And 1 Parts		Possible Solutions:		Compliance Description			Data Compliance Description			
2 STONE STREET	AL AL	Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	112.0	N/A	Grade Break?	N/A	
NIC 1900 MEN	& Man			Yes	Ramp Width (in)	55.0	N/A	Grade Break Slope (%)	0.0	
the Island and	N Marine	5		No	Ramp Slope (%)	10.7	N/A	Grade Break XSlope (%)	0.0	
	1	1		No	Ramp XSlope (%)	3.6				
A Contract 1	2/-			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	10 1	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N. Steller	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
the second s	Share IS			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A State State				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
E OF	1			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	1 4 1	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
		,,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	A An			N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	4.0	
Street 1 Name C	ATALINA AV	_			X Walk 1 Direction	To SE		Road X Slope (%)	0.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.8	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	13.3	

