

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52624	Main St	Main Street: CORMWELL_LN			CONTEMPORARY_PL	Location:	SW			
ADA ID: D391BC2BDC3	5 Ramp T	Ramp Type: Perp			il: Fail Overall (ce: N	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Possible Solutions:						liance Description	Data		
1.76 44	No. Market		-	N/A	Ramp Length (in)	99.0	No	Ramp Slope (%)	9.1	
2 9 9 4	Carl The	Remove & Replace Entire Ramp.		/es	Ramp Width (in)	59.0	Yes	Ramp XSlope (%)	3.1 1.6	
Chi Ka	- Line Mar			N/A	Flare Type LT	55.0 N/A	N/A	Flare Type RT	N/A	
and the second	A 2 10 10 10	6 2		N/A	•••		N/A		N/A N/A	
Contraction of the second	No WARRAN				Flare Slope LT (%)	N/A		Flare Slope RT (%)		
	A. 4533			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
5	State State			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
<u>.</u>		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A ARA AND A	a la la	N/A	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
TUPOItes	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
COLTURA	0 0		1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1.0%.	4	1	N/A	Shared Landing?	N/A				
N PE HER	The second second	PROW/ADA:	M	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	The second se	Not Found, R304.2.2	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	All a second		1	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	y Wash				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
			1	N/A	X Walk 1 Width (in)	63.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	CONTEMPORARY PL				X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A			1/1	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
Stop Condition-Street 1	N/A				,					
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

