

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14235	Main St	Main Street: CAMDEN RD			E_TREMONT_AV		Location: S		
ADA ID: D50EAA1F31CF	Ramp T	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Complianc			o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:									Data
and a state	F. ANHA		-	N/A	Ramp Length (in)	102.0	No	Ramp Slope (%)	8.7
		Remove & Replace Entire Ram	p.	Yes	Ramp Width (in)	102.0	Yes	Ramp XSlope (%)	0.6
	AND F M	4		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1111 See	<u>2</u>		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second secon					,		N/A		
W_TREMONT_AV	1 Bar			N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
1.1.5	Ave			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	S	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		C. C.		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The second se				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
BORLIN I I PAR				N/A	Shared Landing?	N/A			
SI TESI UNI	(real	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E SL ST TIME KS	C AND AND A	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1.1			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	č.			X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
ATA INDE	5		N/A	X Walk 1 Width (in)	145.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name E	TREMONT AV				X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
		······ •				N/A	Î		N/A
						17/7	1		19/5

Yes Surface Condition? (G/P)

Good



