

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14071	Main Str	eet: CLEVELAND_AV	Cross Stre	oot.	E KINGSTON AV			Location:	N
				Cross Street: E_KINGSTON_AV					
ADA ID: D61BF9FB6427	ID: D61BF9FB6427 Ramp Type: Directional1		Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	ALL CALLER	Possible Solutions:	Compliance Description			Data	Data Compliance Description		
	A TE	Remove & Replace Entire Ramp	. N/	Α	Ramp Length (in)	47.0	N/A	Grade Break?	N/A
			Ye	es	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
			No	D	Ramp Slope (%)	9.3	N/A	Grade Break XSlope (%)	0.0
	N gla les		No	D	Ramp XSlope (%)	2.2			
A A A A A A A A A A A A A A A A A A A	A BY MAY		N/	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A HERE	CON CONTRACT		N/	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:	N/	A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	N/	A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
			N/	Α	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	E. C. A.		N/	Α	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	A LON		N/	Α	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:	N/	A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A A A A	CA STORE	R304.2.2, R304.5.3	N/	Α	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
he he he is	1 5 1 E		N/	Α	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	10 1 0 1 M		N/	Α	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			N/	Α	Painted X Walk1?	No		Road Slope (%)	2.8
Street 1 Name	E KINGSTON AV				X Walk 1 Direction	To SW		Road X Slope (%)	1.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.5	N/A	Storm Grate/Utility Hazard?	N/A
			N/	Α	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N/	A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	7.7

