## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21411	21411 Main Street: MONROE_RD			Street:	SARDIS_RD_NORTH	Location:	NE		
ADA ID: D7336FC3DD0C	Ramp Type: BlendTrans2			Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	: 2.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	C POINT	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	3.2
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	0.7
		Equivalent.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	2.8
				N/A	Flare Traversable LT?	No		Flare Traversable RT?	No
Call Call	AT A MARKED			N/A	Landing Length (in)	N/A		DWS Provided?	Yes
	-	Surveyor Notes:		N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
				N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
A BILLING B		LOCATED ON MEDIAN		N/A	Landing X Slope (%)	N/A		DWS Full Width?	No
the RUNC				N/A	Landing Curb? (Y/N)	No		DWS Offset (in)	6.5
SARDIS-				N/A	Shared Landing?	No		DWO Onset (m)	0.0
	- North	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.3
		1		Yes	-	0.0		,	0.7
		Not Found, R305.1.4, R305.2		N/A	Gutter Lip Ht (in) Painted X Walk1?	0.0 Yes		Gutter X Slope (%) Painted X Walk2?	0.7 N/A
G. G.				N/A			N/A		
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
				X Walk 1 Width (in)	112.0		X Walk 2 Width (in)	N/A	
Street 1 Name	SARDIS RD NORTH				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	YieldSign				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.1		Clear Space?	Yes
					Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.3