

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: PROVIDENCE_COUNTRY_CLUBE_ross Street: MCGILL_HEIGHTS_RD Location: NW **Severity Score: Overall Compliance: No** ADA ID: D791D941A17A Ramp Type: Perp Initial Pass/Fail: Fail 12.5

Codes/Mitigation Info/Possible Solution



| Street 1 Name | MCGILL HEIGHTS RD |
|-------------------------|-------------------|
| Stop Condition-Street 2 | StopSign |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

| i cccibic cciation | |
|-------------------------------|---|
| Possible Solutions: | С |
| Remove & Replace Entire Ramp. | |
| • | Y |
| | N |
| | N |
| | N |
| | N |
| Surveyor Notes: | N |
| N/A | N |
| | N |
| | N |
| | N |
| PROW/ADA: | N |
| Not Found, R304.2.2 | N |
| | N |
| | N |
| | |

| The Co | | |
|--------|------|--|
| 狼 | Alk. | |
| | L. | |
| 4.7 | | |



Total Cost:



1850.00

| Field Measurements/Component Compliance | | | | | | | | |
|---|-----------------------|------|-------|-----------------------------|------|--|--|--|
| Compl | iance Description | Data | Compl | liance Description | Data | | | |
| N/A | Ramp Length (in) | 84.0 | No | Ramp Slope (%) | 9.8 | | | |
| Yes | Ramp Width (in) | 70.0 | Yes | Ramp XSlope (%) | 1.3 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | | |
| N/A | Shared Landing? | N/A | | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | | |
| N/A | Gutter Lip Ht (in) | 2.5 | N/A | Gutter X Slope (%) | N/A | | | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | | | |
| | X Walk 1 Direction | To E | | X Walk 2 Direction | N/A | | | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | | | |
| | X Walk 1 Slope (%) | 0.1 | | X Walk 2 Slope (%) | N/A | | | |
| | X Walk 1 X Slope (%) | 2.4 | | X Walk 2 X Slope (%) | N/A | | | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | | | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | | | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | | | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | | | |
| | Obstruction Type | | | Storm Grate/Utility Type | | | | |
| | | N/A | | | N/A | | | |
| | | | Yes | Surface Condition? (G/P) | Good | | | |