cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11882	Main Street: N_PINE_ST Cr				W_5TH_ST	Location:	Е		
ADA ID: D79F3D6349C7	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No					12.5
· · · ·									12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance De		liance Description	Data
		Remove & Replace Curb Ra	amp With	N/A	Ramp Length (in)	52.0	Yes	BlendTrans Slope (%)	4.0
		Two New Directional Ramp	Ramps or	Yes	Ramp Width (in)	54.0	No	BlendTrans XSlope (%)	6.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		s		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
G.G. With a				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1 clas			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1126			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	110.0		X Walk 2 Width (in)	N/A	
Street 1 Name	W 5TH ST	-			X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.6		Clear Space?	N/A
					Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	2.0 N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00	11/4	Obstruction Type	11/4		Storm Grate/Utility Type	174
			5200.00		Obstruction Type	N/A		Storm Grate/Ounity Type	N/A
						IN/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.1