cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9469	Main Str	Cross Street: CLYDE DR					Location:	S	
ADA ID: D7D194663377			Initial Pass/Fail: Fail Overall Compliance: No					17.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		liance Description	Data
		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	60.0	Yes	BlendTrans Slope (%)	3.2
		Two New Directional Ramps or		No	Ramp Width (in)	34.0	Yes	BlendTrans XSlope (%)	1.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
TRD C		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
EUNICALLOU		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	AND AND AND			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
STA TOP.		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The state of the				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	1. 1. 20				X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	-1 6 23				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name B	UNGALOW RD	-			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.1		Clear Space?	N/A
					Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.5 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 320	00.00		Obstruction Type	17/4		Storm Grate/Utility Type	17/5
			00.00		Obstruction Type	N/A		Storm Grate/Ounity Type	N/A
						IN/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

5.7