

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29975 Main Street: DAVID\_COX\_RD Cross Street: LEGACY\_LAKE\_LN Location: NE

ADA ID: D84A8DE2516C Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
LEGACY LAKE LN
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 1850.00

| Field Measurements/Component Compliance |                       |      |      |                             |      |
|---|-----------------------|------|------|-----------------------------|------|
| Compliance Description                  |                       | Data | Comp | liance Description          | Data |
| N/A                                     | Ramp Length (in)      | 61.0 | Yes  | Ramp Slope (%)              | 6.8  |
| No                                      | Ramp Width (in)       | 47.5 | Yes  | Ramp XSlope (%)             | 1.4  |
| N/A                                     | Flare Type LT         | N/A  | N/A  | Flare Type RT               | N/A  |
| N/A                                     | Flare Slope LT (%)    | N/A  | N/A  | Flare Slope RT (%)          | N/A  |
| N/A                                     | Flare Traversable LT? | N/A  | N/A  | Flare Traversable RT?       | N/A  |
| N/A                                     | Landing Length (in)   | N/A  | N/A  | DWS Provided?               | N/A  |
| N/A                                     | Landing Width (in)    | N/A  | N/A  | DWS Contrast?               | N/A  |
| N/A                                     | Landing Slope (%)     | N/A  | N/A  | DWS Length (in)             | N/A  |
| N/A                                     | Landing X Slope (%)   | N/A  | N/A  | DWS Full Width?             | N/A  |
| N/A                                     | Landing Curb? (Y/N)   | N/A  | N/A  | DWS Offset (in)             | N/A  |
| N/A                                     | Shared Landing?       | N/A  |      |                             |      |
| N/A                                     | Gutter Ponding?       | N/A  | N/A  | Gutter Slope (%)            | N/A  |
| N/A                                     | Gutter Lip Ht (in)    | N/A  | N/A  | Gutter X Slope (%)          | N/A  |
| N/A                                     | Painted X Walk1?      | No   | N/A  | Painted X Walk2?            | N/A  |
|   | X Walk 1 Direction    | To W |      | X Walk 2 Direction          | N/A  |
| N/A                                     | X Walk 1 Width (in)   | N/A  | N/A  | X Walk 2 Width (in)         | N/A  |
|   | X Walk 1 Slope (%)    | 2.7  |      | X Walk 2 Slope (%)          | N/A  |
|   | X Walk 1 X Slope (%)  | 3.7  |      | X Walk 2 X Slope (%)        | N/A  |
| N/A                                     | Ramp inside XWalk1?   | N/A  | N/A  | Ramp inside XWalk2?         | N/A  |
|   | Road Slope (%)        | N/A  | N/A  | Clear Space?                | N/A  |
|   | Road X Slope (%)      | N/A  | N/A  | Clear Space to XWalk (in)   | N/A  |
| N/A                                     | Any Obstructions?     | N/A  | N/A  | Storm Grate/Utility Hazard? | N/A  |
|   | Obstruction Type      |      |      | Storm Grate/Utility Type    |      |
|   |                       | N/A  |      |                             | N/A  |
|   |                       |      | Yes  | Surface Condition? (G/P)    | Good |
| - + I                                   |                       | ,    | •    | . ,                         |      |





