

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·										
Intersection ID: 13150	50 Main Street: OAKLAND_AV			Cross	Street:	SUNNYSIDE_AV	Location:	SE		
ADA ID: D84E98218FD9	84E98218FD9 Ramp Type: BlendTrans1			Initial	Pass/Fa	ail: Fail Overall C	o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
- 1 - 1 - 1		Possible Solutions:							liance Description	Data
		Remove & Replace Curb F Two New Directional Ram Equivalent.	Ram	n With	N/A	Ramp Length (in)	57.0	Yes	BlendTrans Slope (%)	4.4
					Yes	Ramp Width (in)	70.0	No	BlendTrans XSlope (%)	2.6
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	An Ing				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
La Contraction and the second					N/A	Landing Length (in)		N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and a state of the state						X Walk 1 Direction	To N		X Walk 2 Direction	To W
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name S	SUNNYSIDE AV	-				X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	3.2
Stop Condition-Street 1	YieldSign					X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	2.2
Street 2 Name	OAKLAND AV				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	YieldSign					Road Slope (%)	2.7		Clear Space?	N/A
	-					Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

16.4