cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27755 Main Street: BALLANTYNE_CROSSING_AV Cros					NOLEN_LN	Location:	<u> </u>		
ADA ID: D88B825ADD44	ID: D88B825ADD44 Ramp Type: BlendTrans1 Ir				ail: Fail Overall (o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Date			a Compliance Description		Data
		Remove & Replace Curb Ran	np With	N/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	3.2
		Two New Directional Ramps	•	Yes	Ramp Width (in)	50.0	No	BlendTrans XSlope (%)	5.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	S.A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6.5 E		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and the second second	and a	-		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A CONTRACTOR OF THE OWNER OWNER OWNER OF THE OWNER OWNE	C C			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	AL AL			N/A	Shared Landing?	N/A			
THE REAL PROPERTY	ROOM STATE	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 VIC	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second second				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name BALLANTYNE CROSSING AV					X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	6.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	6.6		Clear Space?	N/A
					Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.4