## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46190 Main Street: YAUPON_RD Cross Street: LUSTRE_RD						Location:	NE	
ADA ID: D912FD8EB07D Ramp Type: BlendTrans1		Initial Pass	tial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	<u>Cc</u>	Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp W Two New Directional Ramps or	Vith N/.	A Ramp Leng	gth (in) 70.5	Yes	BlendTrans Slope (%)	4.0	
		Ye	s Ramp Widt	h (in) <b>48.0</b>	No	BlendTrans XSlope (%)	2.6	
	Equivalent.	N/.	A Flare Type	LT N/A	N/A	Flare Type RT	N/A	
		N/.	A Flare Slope	e LT (%) N/A	N/A	Flare Slope RT (%)	N/A	
		N/.	A Flare Trave	ersable LT? N/A	N/A	Flare Traversable RT?	N/A	
		N/.	A Landing Le	ngth (in) N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/.	A Landing Wi	dth (in) N/A	N/A	DWS Contrast?	N/A	
	CURB WIDTH 44.0	N/.	A Landing Slo	ope (%) N/A	N/A	DWS Length (in)	N/A	
		N/.	Landing X S	Slope (%) N/A	N/A	DWS Full Width?	N/A	
	-	N/.	A Landing Cu	ırb? (Y/N) N/A	N/A	DWS Offset (in)	N/A	
		N/.	A Shared Lar	nding? N/A				
	PROW/ADA:	N/.	A Gutter Pon	ding? N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.3	N/.	Gutter Lip H	Ht (in) N/A	N/A	Gutter X Slope (%)	N/A	
	· ·	N/.	A Painted X V	Valk1? No	N/A	Painted X Walk2?	No	
	2		X Walk 1 D	irection To W		X Walk 2 Direction	To S	
			X Walk 1 W	/idth (in) N/A		X Walk 2 Width (in)	N/A	
Street 1 Name LUSTRE RD			X Walk 1 S	lope (%) 1.2		X Walk 2 Slope (%)	3.1	
Stop Condition-Street 1 StopSign			X Walk 1 X	Slope (%) 2.9		X Walk 2 X Slope (%)	1.4	
Street 2 Name YAUPON RD		N/.	A Ramp insid	e XWalk1? N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2 None			Road Slope	e (%) 0.8		Clear Space?	N/A	
			Road X Slo	pe (%) <b>1.9</b>	N/A	Clear Space to XWalk (in)	N/A	
		N/.	Any Obstru	ctions? N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	00.00	Obstruction	туре		Storm Grate/Utility Type		
				N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.0