

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

68.0

71.0

6.4

2.8

8.5

5.2

N/A

Intersection ID: 14959 Main Street: EASTLAND MALL DR **Cross Street: CENTRAL AV** Location: Ε Initial Pass/Fail: Fail **Overall Compliance: No** 25 ADA ID: D9A787E1ADCC Ramp Type: Combination1 **Severity Score:** 

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

Yes

No

No

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Ramp XSlope RT (%)

Data

38.0

72.0

5.4

0.5

60.0

48.0

N/A

Yes

To NW

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name Signal Stop Condition-Street 1 **EASTLAND MALL DR** N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.2.2, R304.5.3 N/A N/A N/A N/A N/A N/A



Total Cost:



		X Walk 1 Width (in)	112.0		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	N/A
1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A	
					Obstruction Type	
						N/A
			N/A	Storm Grate/Utility Hazard?	N/A	
				l	Storm Grate/Utility Type	N/A
						N/A
				Yes	Surface Condition? (G/P)	Good
	10				Curb Slope (%)	9.3
	-1-1-1-1		'	,	,	