cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42934	ection ID: 42934 Main Street: HOLLY_PARK_DR 0				Cross Street: BALLINA_WY				S
ADA ID: D9B93F7228CB	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				Location: Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	gatorino	Possible Solutions:					liance Description	Data	
		Remove & Replace Curb Ram	n With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	4.0
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	42.5		BlendTrans XSlope (%)	11.2
			-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the test of te		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3	2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	HOLLY PARK DR				X Walk 1 Slope (%)	5.2		X Walk 2 Slope (%)	5.7
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	7.6		X Walk 2 X Slope (%)	6.8
Street 2 Name	BALLINA WY			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	9.2		Clear Space?	N/A
, · · · · · · · · · · · · · · · · ·					Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		·			51	N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.5