cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15055	Main Str	Main Street: BUCHANAN_ST			SCOTT_AV	Location:	N			
ADA ID: DA0745C48EA3	Ramp Ty	Ramp Type: BlendTrans1			ail: Pass Overall	o Severity Score:	: 0			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	14. 14	Possible Solutions:		Compliance Description Data			Comp	Compliance Description Data		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	89.0	Yes	BlendTrans Slope (%)	2.5	
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	1.8	
		Equivalent.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped	
a the factor of the				N/A	Flare Slope LT (%)	1.8	N/A	Flare Slope RT (%)	1.7	
	AV A			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
	L.			Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes	
A Provide State		Surveyor Notes:		Yes	Landing Width (in)	70.0	Yes	DWS Contrast?	Yes	
E S	CAR MAN	N/A		Yes	Landing Slope (%)	1.0	Yes	DWS Length (in)	24.5	
	No. W.			Yes	Landing X Slope (%)	1.8	Yes	DWS Full Width?	Yes	
	A STATE OF	3		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	4.0	
	- Mary and	PROW/ADA:		N/A	Shared Landing?	No				
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.8	
The states	ANY N.	Not Found, R305.2		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.5	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name E	BUCHANAN ST	_			X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	3.4		Clear Space?	Yes	
					Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A	
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

15.0