cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2684	Main Street: CARDINAL_POINT_RD				Street:	SUMMERGOLD_WY	Location:	SW			
ADA ID: DA1AFDA13308	8 Ramp Type: BlendTrans1			Initial	Pass/Fa	ail: Pass Overall	o Severity Score	0			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data Compliance		liance Description	Data	
		Remove & Replace Curb	Curb Ramp With		N/A	Ramp Length (in)	49.5	Yes	BlendTrans Slope (%)	3.2	
AN ANT		Two New Directional Ramps Equivalent.			Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	0.3	
			•		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped	
					N/A	Flare Slope LT (%)	4.8		Flare Slope RT (%)	1.4	
					N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
SUMMERGOL	D_WY				Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes	
		Surveyor Notes:			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
ter and the second s		N/A			No	Landing Slope (%)	4.2	Yes	DWS Length (in)	25.5	
Marshall 18				Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes		
				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0		
					N/A	Shared Landing?	No				
		PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.4	
	Not Found, R304.2.2-Perp, R304.3.2- Para, R305.2			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0		
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A		
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
Street 1 Name	CARDINAL POINT RD	-				X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A					Road Slope (%)	1.2		Clear Space?	Yes	
						Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A	
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	







No

Curb Slope (%)

8.6