cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



ADA ID: DA9486AB8F64 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Seve	ation: SW erity Score: 10
	erity Score: 10
Codes/Mitigation Info/Possible Solution Field Measurements/Component Complia	ince
Possible Solutions: Compliance Description Data Compliance Description	
Remove & Replace Curb Ramp With N/A Ramp Length (in) 48.0 Yes BlendTrans Slo	
Two New Directional Ramps or No Ramp Width (in) 45.0 No BlendTrans XS	1 ()
Equivalent. N/A Flare Type LT N/A Flare Type RT	1 ()
N/A Flare Slope LT (%) N/A Flare Slope RT	
N/A Flare Traversable LT? N/A N/A Flare Traversable LT?	
N/A Landing Length (in) N/A DWS Provided	
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast	
N/A N/A Landing Vidan (in) N/A DWO contrasts N/A N/A N/A DWO contrasts	
N/A N/A N/A N/A N/A N/A N/A N/A DWS Edigar(h)	
	1) N/A
N/A Shared Landing? N/A	0() N/A
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%	
Not Found, R304.5.1, R304.5.3 N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope	()
N/A Painted X Walk1? No N/A Painted X Walk	-
X Walk 1 Direction To E X Walk 2 Direct	
X Walk 1 Width (in) N/A X Walk 2 Width	
Street 1 Name TRILLIUM FIELDS DR X Walk 1 Slope (%) 0.0 X Walk 2 Slope	()
Stop Condition-Street 1 None X Walk 1 X Slope (%) 4.9 X Walk 2 X Slope	ope (%) 0.5
Street 2 Name ROCKY BROOK CT N/A Ramp inside XWalk1? N/A Ramp inside XWalk1?	Walk2? N/A
Stop Condition-Street 2StopSignRoad Slope (%)3.4Clear Space?	N/A
Road X Slope (%) 2.4 N/A Clear Space to	o XWalk (in) N/A
N/A Any Obstructions? N/A N/A Storm Grate/Ut	Itility Hazard? N/A
Total Cost:\$ 3200.00Obstruction TypeStorm Grate/Ut	tility Type
N/A	N/A

YesSurface Condition? (G/P)NoCurb Slope (%)

Good

13.0





