

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13541Main Street: CENTRAL_AVCross Street: EASTCREST_DRLocation:SWADA ID: DB3EE34D1524Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



| Street 1 Name | EASTCREST DR |
|-------------------------|--------------|
| Stop Condition-Street 2 | Signal |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

| Possible Solutions: | | | | |
|--------------------------------|--|--|--|--|
| Remove & Replace Entire Ramp. | | | | |
| · | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Surveyor Notes: | | | | |
| N/A | | | | |
| | | | | |
| | | | | |
| | | | | |
| PROW/ADA: | | | | |
| Not Found, R304.5.1, R304.2.2, | | | | |
| R304.5.3 | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Total Cost:



1850.00

| Field Measurements/Component Compliance | | | | | | | | |
|---|-----------------------|-------|--------------------|------------------------|-------------------------|------|--|--|
| Comp | liance Description | Data | Comp | liance | Description | Data | | |
| N/A | Ramp Length (in) | 59.5 | No | Ramp | Slope (%) | 8.6 | | |
| No | Ramp Width (in) | 36.5 | No Ramp XSlope (%) | | | 3.9 | | |
| N/A | Flare Type LT | N/A | N/A Flare Type RT | | N/A | | | |
| N/A | Flare Slope LT (%) | N/A | N/A | N/A Flare Slope RT (%) | | | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare | Traversable RT? | N/A | | |
| N/A | Landing Length (in) | N/A | N/A | DWS | Provided? | N/A | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | | N/A | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS | Length (in) | N/A | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A | | |
| N/A | Shared Landing? | N/A | | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutte | r Slope (%) | N/A | | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutte | r X Slope (%) | N/A | | |
| N/A | Painted X Walk1? | Yes | N/A | Paint | ed X Walk2? | N/A | | |
| | X Walk 1 Direction | To SE | | X Wa | lk 2 Direction | N/A | | |
| N/A | X Walk 1 Width (in) | 109.0 | N/A | X Wa | lk 2 Width (in) | N/A | | |
| | X Walk 1 Slope (%) | 7.1 | | X Wa | lk 2 Slope (%) | N/A | | |
| | X Walk 1 X Slope (%) | 1.3 | | X Wa | lk 2 X Slope (%) | N/A | | |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ramp | inside XWalk2? | N/A | | |
| | Road Slope (%) | N/A | N/A | Clear | Space? | N/A | | |
| | Road X Slope (%) | N/A | N/A | Clear | Space to XWalk (in) | N/A | | |
| N/A | Any Obstructions? | N/A | N/A | Storm | n Grate/Utility Hazard? | N/A | | |
| | Obstruction Type | | | Storm | n Grate/Utility Type | | | |
| | | N/A | | | | N/A | | |
| | | | Yes | Surfa | ce Condition? (G/P) | Good | | |
| obil 🏣 | | | | | | | | |