

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14326 Main Street: BALDWIN_AV Cross Street: LUTHER_ST Location: E

ADA ID: DB6EA1EBB08E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 35

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

BALDWIN AV StopSign LUTHER ST StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compli	ance	Description	Data
	N/A	Ramp Length (in)	60.0	No	Ramp	Slope (%)	13.3
	No	Ramp Width (in)	40.0	No	Ramp XSlope (%)		4.7
	N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)		N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	Yes	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
		X Walk 1 Direction	To NW		X Wa	lk 2 Direction	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
		X Walk 1 Slope (%)	3.3		X Wa	lk 2 Slope (%)	0.1
		X Walk 1 X Slope (%)	2.5		X Wa	lk 2 X Slope (%)	1.9
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	1.4	N/A	Clear	Space?	N/A
		Road X Slope (%)	3.8	N/A	Clear	Space to XWalk (in)	N/A

N/A

N/A

N/A

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

Good







N/A

Any Obstructions?

Obstruction Type