## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	ersection ID: N/A Main Street: W_W_T_HARRIS_BV			Cross Street: N/A					Location:	S	
ADA ID: DD62BFA6B388	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: N				ice: N	o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
alle III a		Possible Solutions:			Compliance Description Data			Compliance Description		Data	
3		Remove & Replace Curl	Ramp W	ith	N/A	Ramp Length (in)	93.0	Yes	BlendTrans Slope (%)	3.0	
		Two New Directional Ram	•	-	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	5.5	
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second second		NO LNDG			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
201100					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		2			N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	15 K				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW		
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
Street 1 Name	W W.T. HARRIS BV					X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	2.6	
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	5.4	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	StopSign					Road Slope (%)	2.3		Clear Space?	N/A	
						Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$ 320	0.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.3