cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13437	ntersection ID: 13437 Main Street: TRYSTING_RD Cr					ross Street: WOODWEDGE_DR			
ADA ID: DF33638CA661				Initial Pass/Fail: Fail Overall Compliance: No				Location: o Severity Score:	<u>NE</u> 8.75
· •									0.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	8	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	35.5	Yes	BlendTrans Slope (%)	1.7
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	1.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
8				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
<u>6.</u>	2 Cart	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the states of th		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
TOTAL STATES				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	O PD			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A MAR PORT			N/A	Shared Landing?	N/A				
The second of		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
· · · · · · · · · · · · · · · · · · ·			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
	A ALL				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	WOODWEDGE DR	-			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	. c N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.2		Clear Space?	N/A
,					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
		φ σε				N/A		Clothin Grate/Guilly Type	N/A
						IN/A			IN/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

21.3