

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3555Main Street:SAXONBURY_WYCross Street:WINDY_MEADOW_LNLocation:SEADA ID: DF44EB39CC60Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name WINDY MEADOW LN
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A

Surveyor Notes:

N/A

N/A

PROW/ADA:

Not Found, R304.5.3

Not Found, R304.5.3

Total Cost: \$ 1850.00

Field Measurements/Component Compliance							
Compli		iance Description	Data	Compliance		Description	Data
	N/A	Ramp Length (in)	50.0	Yes	Ramp	Slope (%)	5.0
	Yes	Ramp Width (in)	48.5	No	Ramp	XSlope (%)	7.7
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
		X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
		X Walk 1 Slope (%)	10.5		X Wa	lk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	2.0		X Wa	lk 2 X Slope (%)	N/A
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	N/A	N/A	Clear	Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good





