

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18038	Main Street: INWOOD_DR				Street:	MURRAYHILL_RD	Location:	Ν			
ADA ID: E0DA532778DC	C Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	2 11 10	Possible Solutions:			Compliance Description		Data Compliance Description			Data	
	1/1/2	Remove & Replace En	tire Ram	D.	N/A	Ramp Length (in)	84.0	N/A	Grade Break?	N/A	
	11 15 -			•	Yes	Ramp Width (in)	64.0	N/A	Grade Break Slope (%)	0.0	
AND	1 1 1				Yes	Ramp Slope (%)	3.4	N/A	Grade Break XSlope (%)	0.0	
					No	Ramp XSlope (%)	3.2				
A A A A A A A A A A A A A A A A A A A	Nor I				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	1 L Des				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
TO COONT	AL AN	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	mall.	CURB SLIGHTLY MOD	IFIED		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	and 1				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
the Y				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
2 BKO G C				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
6.	C. Martin	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
3		R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	1 A Maria				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	5			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
				N/A	Painted X Walk1?	No		Road Slope (%)	7.0		
Street 1 Name	INWOOD DR	-				X Walk 1 Direction	To S		Road X Slope (%)	1.2	
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	7.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	1.2	N/A	Storm Grate/Utility Hazard?	N/A	
-					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A		5 51	N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	22.8	

