

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21450	Main Street: STERNCREST_PL			Cross Street: WOODSTREAM_DR				Location:	SE	
ADA ID: E1E7D4FC803B	B Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:						Compliance Description Data				
Contraction in the	The America	Remove & Replace Entire Ram	0.	N/A	Ramp Length (in)	24.0	N/A	Grade Break?	N/A	
A REAL PROPERTY AND A REAL				No	Ramp Width (in)	47.5	N/A	Grade Break Slope (%)	0.0	
	1			Yes	Ramp Slope (%)	0.2	N/A	Grade Break XSlope (%)	0.0	
				No	Ramp XSlope (%)	4.3				
and the second second second	the lot of the second	5		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
WOODSTREAM DR	The second			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	10 10 A	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
e e		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
ACTIVITY REAL STREET			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
PROW/ADA: R304.5.1, R304.5.3				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	R304.5.1, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
5 Sarah			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	2.3	
Street 1 Name S1	<b>FERNCREST PL</b>				X Walk 1 Direction	To SW		Road X Slope (%)	4.1	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.1	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	5.3	

