cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4970	Main Street: SCOTTSMAN_TRACE_DR			Cross Street: HIGHLAND_MEADOW_RD				Location:	SW
ADA ID: E2B8186D62	226 Ramp Ty	Ramp Type: BlendTrans2			ail: Fail Overall	o Severity Score:	12.5		
	Codes/Mitigation Info	Field Measurements/Component Compliance							
Possible Solutions:						liance Description	Data		
			mn With	N/A	Ramp Length (in)	96.0	Yes	BlendTrans Slope (%)	2.8
		Remove & Replace Curb Ra Two New Directional Ramps		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	5.3
Trata -		Equivalent.	5 01	N/A	Flare Type LT	-+0.0 N/A	N/A	Flare Type RT	0.0 N/A
	or the second second			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A A A A A A A A A A A A A A A A A	6			N/A N/A		N/A	N/A	DWS Provided?	N/A N/A
the second se				N/A N/A	Landing Length (in) Landing Width (in)	N/A	N/A N/A	DWS Flowded? DWS Contrast?	N/A N/A
CE DIS	the second			N/A N/A	o ()	N/A	N/A		N/A N/A
N/A				Landing Slope (%)			DWS Length (in)		
PROW/ADA: Not Found, R304.5.3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A		Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	HIGHLAND MEADOW RD				X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	4.2
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	3.4
Street 2 Name	SCOTTSMAN TRACE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	0.7		Clear Space?	N/A
					Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.6