

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53253 Main Street: MARLOWE_AV					Cross Street: ALYSSA_LN				SE
ADA ID: E2C650BC2EEE				Initial Pass/Fail: Fail Overall Compliance: No				Location: o Severity Score:	25
· · · ·			initia	· · · · ·					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Barris Parts	the state of the s	Possible Solutions:		_	liance Description		1	liance Description	Data
	h · · · ·	Remove & Replace Entire Ran	ıp.	N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	8.4
	a de la de l	3		Yes	Ramp Width (in)		No	Ramp XSlope (%)	6.1
	0	1		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
MARLOWEAN		#		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	- 11			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 1 M			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	ter ter	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A The second for the second		,,,,,,,,,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
-0				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ALYSSA LN	-			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00	11/7	Obstruction Type	N/A		Storm Grate/Utility Type	11/27
			1030.00		Obstruction Type	NI/A		Storm Grate/Otility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

