## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2890	Main Street: BROKEN_PINE_LN			Cross Street: EVERGREEN_HOLLOW_DR					Location:	SE
ADA ID: E3ACE9130067	067 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	46.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data	Data Compliance Description		
H Start	1 There	Remove & Replace	e Entire Ramp.		N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	13.5
16 - 1 - A AM	regis - 1				No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	5.4
	A PARTY				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	LON DR				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ER -					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
HER EVEREI					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A Alan	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
The second se	A CO	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6. 15	IN PORT				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
					N/A	Shared Landing?	N/A			
	Mr. Com	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	V Mar Kar	Not Found, R304.	51 R304 2 2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	10 10 100	R304.5.3	5.1, 1(504.2.2,		N/A	Painted X Walk1?	No		Painted X Walk2?	N/A
	A Chan					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
and the same					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BROKEN PINE LN					X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
	DUA .					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type	1073		Storm Grate/Utility Type	
		10101 0001.	ΨI				N/A		otom orato/ounty type	N/A
							N/A			11/7

Yes Surface Condition? (G/P)

Good

