

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

3.5

Intersection ID: 18191	Main St	Main Street: E_WOODLAWN_RD			Cross Street: LONGWOOD DR				SE
								Location:	
ADA ID: E53FBF1D8932 Ramp Type: Para		initiai	Initial Pass/Fail: Fail Overall Compliance: No					12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	ANDA IN IN	Possible Solutions:		Compliance Description D			Data Compliance Description		Data
	10 mile	Remove & Replace Entire Ram	ıp.	N/A	Ramp Length LT (in)	58.0	N/A	Ramp Length RT (in)	61.0
	C The Action			Yes	Ramp Width LT (in)	89.0	Yes	Ramp Width RT (in)	92.0
And	C. X .			Yes	Ramp Slope LT (%)	1.3	No	Ramp Slope RT (%)	10.5
	WT. SHORT			Yes	Ramp XSlope LT (%)	0.9	Yes	Ramp XSlope RT (%)	0.3
E WOODLAWN				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	C C			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	BALLANCA.	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A B C.		ASP LIP 2.0, LT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	MAN SA	5		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	A CARACTER			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:		N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A
A Starter Start	The second	R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	不会的使用。				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
The second second	Car 12			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
1 Martin States	The State Name				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Street 1 Name	LONGWOOD DR				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	1600.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

