

Access Compliance Report Public Rights-of-Way (Curb Ramps)



16.3

Intersection ID: 13143 Main Street: OSMOND_ST Cross Street: BETHEL_RD Location: SE

ADA ID: E5A3BA4BC0BF Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 18.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

BETHAL RD StopSign OSMOND ST None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Ramp Length (in) Yes BlendTrans Slope (%) N/A 59.0 2.5 No No Ramp Width (in) 34.5 BlendTrans XSlope (%) 4.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A **DWS Provided?** N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To N X Walk 2 Direction To W N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 4.7 X Walk 2 Slope (%) 2.6 X Walk 1 X Slope (%) 0.6 X Walk 2 X Slope (%) 4.0 N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 2.4 Clear Space? N/A Road X Slope (%) 3.0 N/A Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good

No

Curb Slope (%)





