

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11414Main Street:LIBETH_STCross Street:SHAMROCK_DRLocation:SEADA ID: E5A639941DB4Ramp Type:ParaInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
None
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

No
Yes
No
No
N/A
N/A
Surveyor Notes:

RT RP < 5%, NO RT SW

N/A
N/A
N/A
N/A
R304.5.1, R304.5.3

N/A

Total Cost: \$ 1600.00

| Compliance Description Date | | Data | Compliance Description | | Data |
|-----------------------------|----------------------|-------|------------------------|-----------------------------|------|
| N/A | Ramp Length LT (in) | 19.5 | N/A | Ramp Length RT (in) | 25.0 |
| No | Ramp Width LT (in) | 42.0 | No | Ramp Width RT (in) | 43.0 |
| Yes | Ramp Slope LT (%) | 8.3 | Yes | Ramp Slope RT (%) | 1.2 |
| No | Ramp XSlope LT (%) | 3.6 | No | Ramp XSlope RT (%) | 3.8 |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.0 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 3.0 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 21.7 |
| | | | I IVA | Curb Slope (70) | 21 |





