

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6141Main Street: CATHEY\_RDCross Street: ENWOOD\_DRLocation:NADA ID: E6335C11BBA5Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 33.75

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name ENWOOD DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:				
Remove & Replace Entire Ramp.				
	ı			
	ı			
	I			
	ı			
Surveyor Notes:	 			
N/A	ı			
	ı			
	ı			
	I			
PROW/ADA:	I			
Not Found, R304.5.1, R304.2.2,				
R304.5.3	ı			
	'			

Total Cost: \$ 1850.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	48.5	No	Ramp Slope (%)	8.6		
No	Ramp Width (in)	46.5	No	Ramp XSlope (%)	5.6		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		





