## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	ID: N/A Main Street: MARLBROOK DR C					FARMPOND_LN	Location:	NE		
ADA ID: E7991C7CB796	Ramp Type: BlendTrans2									
Codes/Mitigation Info/Possible Solution					tial Pass/Fail: Fail Overall Compliance: No Severity Sc Field Measurements/Component Compliance					211.20
Possible Solutions:										
			_					1		Data
		Remove & Replace Curb Ra Two New Directional Ramps Equivalent.	•		N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	3.1
				No	Ramp Width (in)	46.5	No	BlendTrans XSlope (%)	5.8	
					N/A	Flare Type LT	N/A		Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
	In The				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	12 1.2.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A A	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A IN	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
MARLBROOK	C.DR				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
A CONTRACT OF A CONTRACT	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R3	04.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		• • • • • • •		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Land Cart					X Walk 1 Direction	To W		X Walk 2 Direction	To S	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	FARM POND LN	-				X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	5.4
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	5.3		X Walk 2 X Slope (%)	3.2
Street 2 Name	MARLBROOK DR				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	5.6		Clear Space?	N/A
	etopoign					Road X Slope (%)	4.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	4.7 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	¢	3200 00	11/27	Obstruction Type	N/A		•	17/5
		IOIAI COSI.	Φ	3200.00		Орынской туре	N1/A		Storm Grate/Utility Type	NI/A
							N/A			N/A

YesSurface Condition? (G/P)GoodNoCurb Slope (%)16.9





