## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31442 Main Street: LORDEN_AV Cross Street: RIDING_HILL_AV							Location	SW	
	Main Street: LORDEN_AV				Location:				
ADA ID: E844C461AF1A Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description			Data Compliance Description			
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	ith <sup>I</sup>	N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	6.3	
		1	No	Ramp Width (in)	45.5	No	Ramp XSlope (%)	6.0	
		1	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		I	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		I	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		I	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	I	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	I	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		1	N/A	Shared Landing?	N/A				
	PROW/ADA:	1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		1	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To E		X Walk 2 Direction	To N	
		1	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name RIDING HILL AV	_			X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	4.1	
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	6.6		X Walk 2 X Slope (%)	2.0	
Street 2 Name LORDEN AV		1	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSign				Road Slope (%)	5.9	N/A	Clear Space?	N/A	
				Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A	
		I	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 320	00.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

