

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50738 Main Street: RUBIN_LURA_CT Cross Street: LYNN_LEE_CR Location: N **Overall Compliance: No Severity Score:** ADA ID: E846F0DDA3D9 Ramp Type: Perp Initial Pass/Fail: Fail 22.5

Codes/Mitigation Info/Possible Solution



RUBIN LURA CT Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	_				
Remove & Replace Entire Ramp.					
	١				
	ľ				
Surveyor Notes:	ı				
N/A	ı				
	ı				
	ı				
PROW/ADA:					
Not Found, R304.5.1, R304.2.2, R304.5.3	1				
	•				
	ı				
	ı				





Total Cost:



1850.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	10.3		
No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	3.6		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard	? N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		