cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29504	Main Str	Main Street: ANTHEM_CT		Cross Street: ROSS_MOORE_AV				Location:	Ν
ADA ID: E898E4C774DA	Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						Compliance Description	
		Remove & Replace Curb Ram	∖With	N/A	Ramp Length (in)	74.5		BlendTrans Slope (%)	<u>Data</u> 3.8
		Two New Directional Ramps of		Yes	Ramp Width (in)	61.0	No	BlendTrans XSlope (%)	6.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
4				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
An		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
No march		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
5 B				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
- <u>5</u>	ALL COL			N/A	Shared Landing?	N/A			10/2
	E.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	100			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
16 1 9 A A	the last	Not Found, R304.5.3		N/A	Painted X Walk1?		N/A	Painted X Walk2?	No
	A COLORING			N/A	X Walk 1 Direction	To SW	IN/A	X Walk 2 Direction	To SE
					X Walk 1 Width (in)	10 SVV N/A		X Walk 2 Width (in)	N/A
Street 1 Name ANTHEM CT									
Street 1 Name Stop Condition-Street 1					X Walk 1 Slope (%)	2.2 5.4		X Walk 2 Slope (%)	6.6 1.8
•	StopSign			N1/A	X Walk 1 X Slope (%)			X Walk 2 X Slope (%)	-
Street 2 Name	ROSS MOORE AV			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	4.8		Clear Space?	N/A
					Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A
		T () O (N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.1