

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15707	Main Street: DORCHESTER_PL			Cross Street: POINDEXTER_DR			Location:	NW	
ADA ID: E9D2E937B3FC	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	33.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
	State Car	Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	24.0	N/A	Grade Break?	N/A
	2 A			No	Ramp Width (in)	43.0	N/A	Grade Break Slope (%)	0.0
7 5 6 A 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5	- 14			Yes	Ramp Slope (%)	5.1	N/A	Grade Break XSlope (%)	0.0
T. MERCA LANGE	Erman Arts			No	Ramp XSlope (%)	9.0			
MAR A LANGE	Wite.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
S A	Carlos 3	4		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	AN TO	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
J. J	AN THE	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	- T- P			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
TR PL E	the friend			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
BOBOLESULATE 6.	Traffic			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
U.C.	C BU -	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.1, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	11-29			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	1 2 22	2 2		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	FUR	3		N/A	Painted X Walk1?	No		Road Slope (%)	3.3
Street 1 Name DORCH	IESTER PL	-			X Walk 1 Direction	To SE		Road X Slope (%)	3.7
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.7	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.0)	Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	2.7

