


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8615	Main Street: DARBY_AV	Cross Street: NELSON_AV	Location:	N
ADA ID: EAAA0E0230F1	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 1.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance									
	Possible Solutions:		Compliance			Description			Data			
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		46.0		Yes	Ramp Slope (%)		6.7	
			Yes	Ramp Width (in)		48.0		No	Ramp XSlope (%)		2.5	
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A	
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A	
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A	
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A	
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A	
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A	
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A	
Surveyor Notes:		N/A			N/A		N/A		DWS Offset (in)		N/A	
PROW/ADA:		Not Found, R304.5.3			N/A		N/A					
					N/A		N/A		Gutter Slope (%)		N/A	
					N/A		N/A		Gutter X Slope (%)		N/A	
					N/A		No		Painted X Walk2?		N/A	
							To SW		X Walk 2 Direction		N/A	
					N/A		N/A		X Walk 2 Width (in)		N/A	
							3.1		X Walk 2 Slope (%)		N/A	
							9.9		X Walk 2 X Slope (%)		N/A	
					N/A		N/A		Ramp inside XWalk2?		N/A	
							N/A		Clear Space?		N/A	
							N/A		Clear Space to XWalk (in)		N/A	
					N/A		N/A		Storm Grate/Utility Hazard?		N/A	
									Storm Grate/Utility Type			
							N/A				N/A	
									Yes		Surface Condition? (G/P)	
											Good	

