

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12279 Main Street: S_MINT_ST Cross Street: W_MARTIN_LUTHER_KING_JR_BV Location: ADA ID: EB438778655E Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



Street 1 Name S MINT ST Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

| 1 COSIDIC COIGHOIL | | |
|-------------------------------|----|--|
| Possible Solutions: | C | |
| Remove & Replace Entire Ramp. | | |
| | Ye | |
| | N/ | |
| Surveyor Notes: | N/ | |
| N/A | N/ | |
| | N/ | |
| | N/ | |
| | N/ | |
| PROW/ADA: | N/ | |
| Not Found, R304.2.2 | N/ | |
| | N/ | |
| | N/ | |
| | | |

Total Cost: 1850.00

| Field Measurements/Component Compliance | | | | | | | |
|---|-----------------------|-------|------|-----------------------------|------|--|--|
| Comp | liance Description | Data | Comp | oliance Description | Data | | |
| N/A | Ramp Length (in) | 99.0 | No | Ramp Slope (%) | 8.8 | | |
| Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 0.8 | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | |
| N/A | Shared Landing? | N/A | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | | |
| N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A | | |
| | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A | | |
| N/A | X Walk 1 Width (in) | 172.0 | N/A | X Walk 2 Width (in) | N/A | | |
| | X Walk 1 Slope (%) | 3.5 | | X Walk 2 Slope (%) | N/A | | |
| | X Walk 1 X Slope (%) | 4.5 | | X Walk 2 X Slope (%) | N/A | | |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A | | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | | |
| | Obstruction Type | | | Storm Grate/Utility Type | | | |
| | | N/A | | | N/A | | |
| | | | Yes | Surface Condition? (G/P) | Good | | |





