

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15740	Main Street: WRISTON_PL			Cross Street: DORCHESTER_PL				Location:	S
ADA ID: EBA6FF898A41	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score:		22.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	and interni	Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	63.0	N/A	Grade Break?	N/A
A A A A A A A A A A A A A A A A A A A	1 BUCA			No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0
A MARY SAME	AL			No	Ramp Slope (%)	10.4	N/A	Grade Break XSlope (%)	0.0
The second second				No	Ramp XSlope (%)	3.5			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the state of the s	A. P.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
DORGHASTIAL &		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		DWS WARPED		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
		_		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	OL CONTRACT			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	12	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A STATE AND A STAT	The same	R304.5.1, R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	1429-22	, ,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
A start and the	1/2.			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	0.5
Street 1 Name	WRISTON PL				X Walk 1 Direction	To NE		Road X Slope (%)	3.0
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.0	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	3.4

