

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13255Main Street: CENTRAL_AVCross Street: IRIS_DRLocation:SWADA ID: EC587DD227D7Ramp Type: ParaInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name	IRIS DR
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

1 Ossible Solution	
Possible Solutions:	Com
Remove & Replace Entire Ramp.	N/A
•	Yes
	No
	No
	N/A
	N/A
Surveyor Notes:	N/A
DAMAGED RT FL	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.3.2, R304.5.3	N/A
	N/A
	N/A

		A.J.'s 338-5	AUTO 1933	
	*	**		
7				
	分 多,		9	



Total Cost:



1600.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Compl	iance Description	Data		
N/A	Ramp Length LT (in)	37.0	N/A	Ramp Length RT (in)	34.0		
Yes	Ramp Width LT (in)	85.5	Yes	Ramp Width RT (in)	76.5		
No	Ramp Slope LT (%)	8.7	Yes	Ramp Slope RT (%)	5.7		
No	Ramp XSlope LT (%)	2.8	No	Ramp XSlope RT (%)	4.2		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
			N/A	Curb Slope (%)	3.6		