## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-								
Intersection ID: 44462	Main Str	eet: AMES_HOLLOW_RD	Cross	ss Street: OLD_ASH_CT				Location:	Ν	
ADA ID: EC7B17004CC5	Ramp Ty	Ramp Type: BlendTrans1 Initi			ail: Fail Overall	o Severity Score:	25			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Comp				Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	49.0		BlendTrans Slope (%)	<u>Data</u> 2.9	
		Two New Directional Ramps or	VVILII	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	10.6	
		Equivalent.		N/A	Flare Type LT		N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A	
		-		N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A	
	MOI			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	OLALASIA	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	6			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A N/A	
the second secon			N/A	Shared Landing?	N/A	IN/A	DWS Oliset (III)	N/A		
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	1114 14: 1				0			,		
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?		N/A	Painted X Walk2?	No	
	· //// * .				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	AMES HOLLOW RD				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	1.7	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	8.6	
Street 2 Name	OLD ASH CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	StopSign				Road Slope (%)	8.9		Clear Space?	N/A	
					Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

20.0