

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: KENSAL_GREEN_DR Intersection ID: N/A **Cross Street: ORKNEY_CT** Location: SW **Overall Compliance: No** ADA ID: EC867B80C978 Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 10

Codes/Mitigation Info/Possible Solution



ORKNEY CT Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Remove & Replace Entire Ramp.	No Yes
Remove & Replace Entire Ramp.	No Ye: No
·	Ye: No
	No
	NI//
	N/A
	N/A
surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
ROW/ADA:	N/A
R304.5.1, R304.5.3	N/A
,	N/A
	N/A
	N/A

		N/
		N/
PROW/ADA:		N/
R304.5.1, R304.5.3		N/
,		N/
		N/
		N/
		N/
		N/
Total Cost:	\$ 1600.00	

Field Measurements/Component Compliance									
Comp	liance Description	Data	Comp	liance Description	Data				
N/A	Ramp Length (in)	46.0	N/A	Grade Break?	N/A				
No	Ramp Width (in)	47.5	N/A	Grade Break Slope (%)	0.0				
Yes	Ramp Slope (%)	1.1	N/A	Grade Break XSlope (%)	0.0				
No	Ramp XSlope (%)	2.4							
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A				
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A				
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	No		Road Slope (%)	0.7				
	X Walk 1 Direction	To NE		Road X Slope (%)	1.9				
	X Walk 1 Width (in)	N/A		Clear Space?	N/A				
	X Walk 1 Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A				
	X Walk 1 X Slope (%)	1.9	N/A	Storm Grate/Utility Hazard?	N/A				
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type					
N/A	Any Obstructions?	N/A			N/A				
	Obstruction Type		Yes	Surface Condition? (G/P)	Good				
		N/A	N/A	Curb Slope (%)	5.3				





